Hi All,

This is the weekly test report for Yocto1.1 20110817 build. There are three new bugs were found. Failed to install the sato-sdk image and lsb-sdk image on Sugarbay and Jasperforest. Latest qemu build failed on autobuilder. The images of Blacksand and Crownbay not build out on autobuilder. I2C and standby issues still exist on eMenlow. For bug fixing, broken ldd and libsdl.so issues fixed on Sugarbay. Rpm package can install on Qemuarm in current build.

Note： The test report is archived@ https://wiki.yoctoproject.org/wiki/Yocto_1.1_Weekly_Test_Report

Test Summary:

Test Result Summary			
Component	**Target**	**Status**	**Comments**
BSP	SugarBay	GOOD	Failed to install image due to couldn't find device;
	CrownBay-emgd	BLOCK	Not build out on autobuilder.
	JasperForest	GOOD	Failed to install image due to couldn't find device;I/OAT DMA engine init failed
	Blacksand	BLOCK	Not build out on autobuilder.
	eMenlow	GOOD	I2C_transfer error; Standby failed;
	Beagleboard	BLOCK	RPM package can not be installed.
	Routerstationpro	BLOCK	Everything runs well
	Mpc8315e-rdb	GOOD	Everything runs well
QEMU	qemux86	BLOCK	The image build failed.
	qemux86-64	BLOCK	The image build failed.
	qemuarm	GOOD	Everything runs well
	qemuppc	BUGGY	Unfs does not work with qemuppc
	qemumips	BLOCK	The image can not boot up.
ADT		BLOCK	Toolchains build failed.

   	Critical bugs, more than 50% test cases are blocked
   	Only Normal, Minor or Enhancement bugs, or less than 10% test cases failed
   	Normal, Major and Critical bugs, and more than 10% test cases failed

Detailed Test Result for each component				
Target	**Total TCs**	**Not Run**	**Passed**	**Failed**	**Not testable (Blocked)**
Sugarbay Sato-SDK	62	0	61	1 (bug 1387)	0

Jasperforest lsb-SDK	34	0	32	2 (bug 1387, 1188)	0
n450 Sato-SDK	58	0	0	0	58
eMenlow Sato-SDK	58	0	56	2 (bug 310, 503)	0
Crownbay-Sato-SDK	59	0	0	0	59
Beagleboard Sato-SDK	40	0	0	0	40 (bug 1381)
Routerstationpro Sato-SDK	33	0	0	0	33 (bug 1381)
Mpc8315e-rdb Sato-SDK	36	0	36	0	0
Qemux86-64 Sato	30	0	0	0	30
Qemux86-64 Sato-SDK	35	0	0	0	35
Qemux86 Sato	30	0	0	0	30
Qemux86 Sato-SDK	35	0	0	0	35
Qemumips Sato	30	0	29	1 (bug 1234)	0
Qemumips Sato-SDK	35	0	0	0	35 (bug 1381)
Qemuppc Sato	22	0	21	1 (bug 414)	0
Qemuppc Sato-SDK	27	0	26	1 (bug 414)	0
Qemuarm Sato	30	0	29	1 (bug 1234)	0
Qemuarm Sato-SDK	35	0	34	1 (bug 1234)	0
ADT	6	0	0	0	6 (bug 1382)
Total	695	0	324	10	361

Commit Information

Tree/Branch: Poky/Master

Meta Branch: Master

Poky commit id: 978cdd5cb5b445f1cf406296444cb57cd8aa526a

Issue Summary

Component		Bug Number	Target Milestone
System & Core OS	**Installation & boot**	New! Bug 1387 - [Sugarbay/Jasperforest] Failed to install image due to couldn't find device	---
	System Usage	Bug 503 - [emenlow] system cannot enter S3	1.1

		standby mode	
		Bug 883 - [Sugarbay] GFX 3D game test fail to run with sugarbay BSP image due to libsdl.so	1.1
		Bug 1234: No response when I click the 'Install/Remove Software' icon	1.1 M4
	Other	Bug 310 - [eMenlow] i2c_transfer error on e-Menlow	1.1
		Bug 1188 - [japerforest] I/OAT DMA engine init failed	1.1
		New! Bug 1381: lttng-ust do_compile failed on autobuilder for beagleboard with 20110817 build	1.1
		New! Bug 1382: gcc-crosssdk-intermediate and gcc-runtime build failed on autobuilder for all toolchain with 20110817 build	1.1

Verified Fixed Bug:

----

1. Bug 1352 - [qemuarm] RPM package can not be installed with 20110806 build
2. Bug 1236 - Broken ldd due to wrong path for ld.so