




Hi All,

This is the weekly test report for Yocto1.1 20110901 build. There are three new bugs found. Crownbay/ADT/Beagleboard test are blocked since the images build failed. No emgd driver package found which cause the Crownbay image build failed. No space left on builder3 which cause the toolchains images build failed. Ltngng-ust do\_compile failed which cause Beagleboard image build failed. Xinit error info still be given output to console after login prompt for mpc8315e-rdb. The rpm/zypper install/remove consume disk space issue still exists, No icons shown on X desktop with sato image issue exists in current build. The issue of function 'BUILDSPEC' failed for libpthread-stubs still exist also.

The test report is archived @ [https://wiki.yoctoproject.org/wiki/Yocto\\_1.1\\_Weekly\\_Test\\_Report](https://wiki.yoctoproject.org/wiki/Yocto_1.1_Weekly_Test_Report)

### Test Summary:

Test Result Summary			
Component	Target	Status	Comments
BSP	SugarBay	GOOD	Everything runs well
	CrownBay-emgd	BLOCK	Image build failed.
	JasperForest	GOOD	I/OAT DMA engine init failed;
	Blacksand	GOOD	Everything runs well
	eMenlow	GOOD	I2C_transfer error; Standby failed;
	Beagleboard	BLOCK	Image build failed.
	Routerstationpro	GOOD	Everything runs well
	Mpc8315e-rdb	GOOD	Everything runs well
QEMU	qemux86	GOOD	Everything runs well
	qemux86-64	GOOD	Everything runs well
	qemuarm	GOOD	Everything runs well
	qemuppc	GOOD	Unfs does not work with qemuppc
	qemumips	GOOD	Everything runs well
ADT		BLOCK	Toolchain images build failed.

	Critical bugs, more than 50% test cases are blocked
	Only Normal, Minor or Enhancement bugs, or less than 10% test cases failed
	Normal, Major and Critical bugs, and more than 10% test cases failed

Detailed Test Result for each component					
Target	Total TCs	Not Run	Passed	Failed	Not testable (Blocked)
Sugarbay Sato-SDK	62	0	62	0	0
Jasperforest Isb-SDK	32	0	31	1 (bug 1188)	0
n450 Sato-SDK	58	0	58	0	0
eMenlow Sato-SDK	58	0	56	2 (bug 310, 503)	0
Crownbay-Sato-SDK	59	0	0	0	59 (bug 1444)
Beagleboard	40	0	0	0	40 (bug 1381)
Routerstationpro	33	0	33	0	0
Mpc8315e-rdb	36	0	36	0	0
Qemux86-64 Sato	30	0	28	2 (bug 1174, 1234)	0
Qemux86-64 Sato-SDK	35	0	33	2 (bug 1174, 1234)	0
Qemux86 Sato	30	0	28	2 (bug 1174, 1234)	0
Qemux86 Sato-SDK	35	0	33	2 (bug 1174, 1234)	0
Qemumips Sato	30	0	29	1 (bug 1234)	0
Qemumips Sato-SDK	35	0	34	1 (bug 1234)	0
Qemuppc Sato	22	0	21	1 (bug 414)	0
Qemuppc Sato-SDK	27	0	26	1 (bug 414)	0
Qemuarm Sato	30	0	29	1 (bug 1234)	0
Qemuarm Sato-SDK	35	0	34	1 (bug 1234)	0
ADT	6	0	0	0	6
<b>Total</b>	<b>693</b>	<b>0</b>	<b>571</b>	<b>17</b>	<b>105</b>

### Commit Information

-----

Tree/Branch: Poky/Master

Poky Commit id: 705ec50edda7f7fb8c132238fe3f1477384a470e

Meta Branch: Master

Meta commit id: 902d2f3c919cd1d870dc8d35a7521cbba42e53ea

## Issue Summary

-----

Component		Bug Number	Target Milestone
System & Core OS	System Usage	Bug 503 - [emenlow] system cannot enter S3 standby mode	1.1
		Bug 1082 - [x86_64] No icons shown on X desktop with sato image	1.0 M2
		Bug 1174: [zypper/rpm] package install/removal costs lots of disk space	1.1 M3
		Bug 1234: No response when I click the 'Install/Remove Software' icon	1.1 M4
	Other	Bug 310 - [eMenlow] i2c_transfer error on e-Menlow	1.1
		Bug 1188 - [japerforest] I/OAT DMA engine init failed	1.1
		Bug 1326 - Function 'BUILDSPEC' failed for libpthread-stubs	1.1 M4
		Bug 1381: lttng-ust do_compile failed on autobuilder for beagleboard with 20110817 build	1.1
		<b>New!</b> Bug 1436 - No space left on builder3	1.1 M4
		<b>New!</b> Bug 1444 - There is no emgd driver when build Crownbay images	1.1 M4
<b>New!</b> Bug 1447: [mpc8315e-rdb] xinit error info still be given output to console after login prompt	1.1		