

Hi All,

This is weekly test report for Yocto1.1 M3 RC1 build. There are four new bugs found. All images for Intel BSP not build out. Qemuarm and beagleboard images build failed on autobuilder. Arm/mips/ppc toolchain build failed also. Both sato and sato-sdk images for Qemux86-64 boot failed. Wrong path to ld.so for x86_64 toolchain. The rpm/zypper install/removal consume disk space issue still exists. Install/Remove Software issue exist also. For bug fixing, IPC issue on routerstationpro fixed.

The test report is archived
@https://wiki.yoctoproject.org/wiki/Yocto_1.1_Milestone_Test_Report

Test Summary:

Test Result Summary			
Component	Target	Status	Comments
BSP	SugarBay	BLOCK	Image not build out
	CrownBay-emgd	BLOCK	Image not build out
	JasperForest	BLOCK	Image not build out
	Blacksand	BLOCK	Image not build out
	eMenlow	BLOCK	Image not build out
	Beagleboard	BLOCK	Image build failed
	Routerstationpro	GOOD	Everything runs well
	Mpc8315e-rdb	GOOD	Everything runs well
QEMU			package install/removal costs lots of disk space; "Install/Remove" icon can't work.
	qemux86	GOOD	
	qemux86-64	BLOCK	Images boot failed.
	qemuarm	BLOCK	Image build failed
	qemuppc	BUGGY	unfs does not work with qemuppc
	qemumips	GOOD	Everything runs well
ADT		BLOCK	arm/mips/ppc's toolchain build failed; wrong path to ld.so for x86_64 toolchain.



Critical bugs, more than 50% test cases are blocked

Only Normal, Minor or Enhancement bugs, or less than 10% test cases failed

Normal, Major and Critical bugs, and more than 10% test cases failed

Detailed Test Result for each component					
Target	Total TCs	Not Run	Passed	Failed	Not testable (Blocked)
Sugarbay Sato-SDK	62	0	0	0	62
Jasperforest Sato-SDK	34	0	0	0	34
n450 Sato-SDK	58	0	0	0	58
eMenlow Sato-SDK	58	0	0	0	58
Crownbay-Sato-SDK	59	0	0	0	59
Beagleboard	40	0	0	0	40(bug 1313)
Routerstationpro	33	0	33	0	0
Mpc8315e-rdb	36	0	36	0	0
Qemux86-64 Sato	30	0	0	0	30
Qemux86-64 Sato-SDK	35	0	0	0	35
Qemux86 Sato	30	0	28	2 (bug 1174, 1234)	0
Qemux86 Sato-SDK	35	0	33	2 (bug 1174, 1234)	0
Qemumips Sato	30	0	29	1 (bug 1234)	0
Qemumips Sato-SDK	35	0	34	1 (bug 1234)	0
Qemuppc Sato	22	0	21	1 (bug 414)	0
Qemuppc Sato-SDK	27	0	26	1 (bug 414)	0
Qemuarm Sato	30	0	0	0	30
Qemuarm Sato-SDK	35	0	0	0	35
ADT	6	0	0	0	6(bug 1314, 1318)
Total	695	0	240	8	447

Commit Information

Tree/Branch: Poky-contrib/master_under_test

Poky Commit id: 2f3994545e757efc575341f2b984a62a0a3441fd

Issue Summary

Component		Bug Number	Target Milestone
System & Core OS	System Usage	Bug 1234: No response when I click the 'Install/Remove Software' icon	1.1 M4
		Bug 1174: [zypper/rpm] package install/removal costs lots of disk space	1.1 M3
		New! Bug 1317 - [Qemux86-64]sato and sato-sdk images boot failed	--
	Other	New! Bug 1313: libzypp do_compile failed on autobuilder for beagleboard with 20110730 build	1.1 M3
		New! Bug 1314: toolchain do_populate_sdk failed on autobuilder for arm/mips/ppc with 20110730 build	1.1 M3
		New! Bug 1318: [Toolchain] wrong path to ld.so for x86_64 toolchain.	1.1
ADT		Bug 414: [PPC] kernel panic when booting poky-image-sdk-qemuppc through UNFS	1.1 M3

Verified Fixed Bug:

1. [\[Bug 1161\]](#) [LTP] All IPC related cases failed with Yocto 1.1 M1 build on routerstationpro